

Repair packages

APPLICABLE FROM JANUARY 1ST, 2024

MANDATORY :

All requests to return equipment must be **made by the distributor** via the extranet.virax.com website.

See the full returns procedure at www.virax.com, under After-Sales Service.

Ref.	Description	Price 2024 € excl VAT	DG
760006	REPAIR CROSSBOW 2500/01/03	88,70	V7
760012	REPAIR RAM 240201	384,10	V7
760013	REPAIR RAM 240202	384,10	V7
760014	REPAIR RAM 240203	474,40	V7
760015	REPAIR RAM 240801	384,10	V7
760016	REPAIR RAM 240802	384,10	V7
760017	REPAIR RAM 240803	536,60	V7
760018	REPAIR VAL 35 291000	218,60	V7
760019	REPAIR VAL 35E 291001	274,00	V7
760020	REPAIR VAL 80 291200	330,10	V7
760021	REPAIR VAL 80E 291201	469,20	V7
760022	REPAIR VAL 90 292030	549,10	V7
760023	REPAIR SIBERIA® 221070	358,10	V7
760024	REPAIR BENDER 2518	370,60	V7
760026	REPAIR I10	274,00	V7
760031	REPAIR GAS CONTROLLER 262080	80,40	V7
760033	REPAIR TEST PUMP 262035	143,00	V7
760034	REPAIR PHENIX III 230V 137563	274,00	V7
760037	REPAIR VIRAFAL®	695,50	V7
760038	REPAIR MINI-CRIMPER 253350	87,50	V7
760039*	CALIBRATION M21+/ML21+/M2X/L2X/P25+	63,50	V7
760040	REPAIR M21+/ML21+/M2X/L2X	349,80	V7
760041	REPAIR VIPER® P25+	430,80	V7
760045	REPAIR VIPER® I26	271,30	V7

* The check (760039) will be free if a repair on M21+/ML21+/M2X/L2X/P25+ (réf. 760040 et 760041) is necessary.

A package includes a **diagnosis**, a **repair**, a **change of the necessary parts** and a **check of the equipment**.

The repair carried out and the parts changed are indicated on the return delivery note associated with the machine.

All replaced parts are guaranteed for 6 months.

Your SAS contact : sav@virax.com

NB : You can download this document on www.virax.com, section After Sales Service